Insured/Applicant Name:	Sample Report	Application / Policy #:
Address Inspected: 1112	0 Sample St, Parkland, FL 33076	
Actual Year Built: 1989	D	Date Inspected: 04/18/2023
Minimum Photo Requirer	nents	
Dwelling: Each side	Roof: Each slope 🗹 Plumbing: Water heater, under	er cabinet plumbing/drains, exposed valves
Main electrical service	e panel with interior door label	

 \blacksquare Electrical box with panel off

All hazards or deficiencies noted in this report

A Florida-licensed inspector must complete, sign and date this form.

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System Separate documentation of any aluminum wiring re	emediation must be provid	led and certified by a lice	ensed electrician.
Main Panel Type: ☑ Circuit breaker □ Fuse Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes	🗆 No (explain)	Second Panel Type: ☑ Circuit breake Total Amps: 200 Is amperage sufficient f	r □Fuse or current usage? ☑Yes □No (explain)
Indicate presence of any of the following:			
Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, de * If single strand (aluminum branch) wiring, provi Connections repair via COPALUM crimp Connections repair via AlumniConn			tion of all work must be provided.
Hazards Present Hazards Present Blowing fuses Empty sockets Loose Wiring Tripping breakers Improper grounding Corrosion Double taps		 Exposed wiring Over fusing Unsafe wiring Improper breaker Scorching Other (explain) 	size
General condition of the electrical system: 🗹	Satisfactory Unsatisfac	tory (explain)	
Supplemental information			
Main Panel Panel age: <u>1989</u> Year last updated: <u>Unknown</u> Brand/Model: <u>Unverified</u>	Second Panel Panel age: <u>1989</u> Year last updated: <u>Unkn</u> Brand/Model: <u>Siemens</u>	own	Wiring Type

Pro Inspectors 04/18/2023

HVAC System

Central heat: ☑ Yes □ No

If not central heat, indicate primary heat source and fuel type: ____

Are the heating, ventilation and air conditioning systems in good working order? 🗹 Yes 🗌 No (explain)

Date of last HVAC servicing/inspection: <u>N/A</u>

Hazards Present

Wood burning stove or central gas fireplace*not*professionally installed? □ Yes ☑ No

Space heater used as primary heat source? ☐ Yes ☑ No

Is the source portable? ☐ Yes ☑ No

Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?

Supplemental Information

Age of system: 2016/2017

Year last updated: <u>N/A</u>

(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)

Plumbing System	
Is there a temperature pressure relief valve on the water heater? \square Yes Is there any indication of an active leak? \square Yes \square No Is there any indication of a prior leak? \square Yes \square No Water heater location: <u>Garage</u>	□ No
General condition of the following plumbing fixtures and connection	is to applicances:
Satisfactory Unsatisfactory N/A Dishwasher Image: Constraint of the second se	Satisfactory Unsatisfactory N/A Toilets Image: Constraint of the second secon
Supplemental Information	
Age of Piping System: <u>X</u> Original to home <u>Completely re-piped</u> Partially re-piped (Provide year and extent of renovation in the comments below) 2003	Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify)

Roof (With photos of each roof slope, this section can take the place of	the Roof Inspection Form.)
Predominant Roof	Secondary Roof
Covering material: Concrete Tile	Covering material:
Roof age (years): 1	Roof age (years):
Remaining useful life (years): 29	Remaining useful life (years):
Date of last roofing permit: <u>6/29/22</u>	Date of last roofing permit:
Date of last update: 2022	Date of last update:
If updated (check one):	If updated (check one):
✓ Full Replacement	Full Replacement
Partial Replacement	Partial Replacement
% of replacement	% of replacement
Overall condition:	Overall condition:
☑ Satisfactory	□ Satisfactory
Unsatisfactory (explain below)	Unsatisfactory (explain below)
Any visible signs of damage / deterioration?	Any visible signs of damage / deterioration?
(check all that apply and explain below)	(check all that apply and explain below)
□ Cracking	□ Cracking
	Cupping/Curling
Excessive granule loss	Excessive granule loss
\Box Exposed asphalt	\Box Exposed asphalt
☐ Missing/loose/cracked tabs or tiles	Exposed felt
Exposed felt	☐ Missing/loose/cracked tabs or tiles
\Box Soft spots in decking	\Box Soft spots in decking
□ Visible hail damage	□ Visible hail damage
Any visible signs of leaks 🛛 Yes 🗹 No	Any visible signs of leaks 🛛 Yes 🖾 No
Attic/underside of decking \Box Yes \blacksquare No	Attic/underside of decking □ Yes □ No
Interior ceilings TYes Mo	Interior ceilings I Yes I No

Additional Comments/Observ	ations(use additional pages	; if needed):	
All 4-Point Inspection Formsmust be con I certify that the above statements are tr	, ,	Florida-licensed inspector.	
	Home Inspector	HI8149	04/18/2023
Inspector Signature	Title	License Number	Date
Pro Inspectors	Home Inspector	954.283.8989	-
Company Name	License Type	Work Phone	

Pro Inspectors 04/18/2023

Special Instructions:This sample4-Point Inspection Formincludes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations


Exterior Photos



Electrical System

Panel Photos





HVAC System

HVAC Equipment



Plumbing System

Water Heater





Under cabinet plumbing & drains















Plumbing



























Roof

Photos of Each Slope







Permit #EBP22-003390 ____

mit Info	Site Info	Contacts (3)	Inspections(6)	Chronology (1)
Reviews(4)				
	Type:	EPERMIT REROOF		
	Subtype:	TILE		
Descriptio	on of Work:	re-roof tile		
	Status:	CLOSED		
Ap	plied Date:	6/20/2022		
App	roved Date:	6/29/2022		
is	isued Date:	7/6/2022		
FA	naled Date:	10/3/2022		
Expla	ration Date:	1/2/2023		